



# MONUMENT RECORD

Corner ID: **VanBu\_U23**

## Quarter Corner

Sections 35 & 36 - T08N-R02W, 2nd P.M.  
Van Buren Township, Monroe County, Indiana


**PHOTO IDENTIFIED:** *Photo Date: 06/27/2022*



*Photo Orientation & Description: Looking north at Van\_Bu\_U23*



*Photo Orientation & Description: Looking down at VanBu\_U23*



*Photo Orientation & Description: Looking east at Van\_Bu\_U23*



*Photo Orientation & Description: Looking south at VanBu\_U23*

### ORIGINAL OR SUBSEQUENT SURVEY EVIDENCE FOUND: *Include, search area or areas, search procedure, etc.*

*Date of Field work/Search: 06/27/2022 By: JG & HJ Monument Found: Limestone BTs or Reference Objects Found: n/a Project #: Van Buren Preservation Field Book: 54/67 Equipment: The basis of bearings is Grid North System NAD83(2011)/Indiana West NAVD 88, Epoch 2010.0000, geoid12b\_conus.db3, US Survey Feet, derived from GPS observations utilizing the Indiana Real-Time Network (INCORS). Coordinate data was collected with a Javad Triumph LS Network Rover. Coordinates are available upon request. Distances to witness ties were collected with a Leica Disto laser distance meter. Bearings to witness ties were collected with the internal magnetic compass of the Javad Triumph LS and were automatically adjusted to grid north and are approximately shown hereon for reference. Priority should be given to provided distances over bearings. Notes: All witness photos on file in the Monroe County Surveyors Office.*



**OFFICE OF THE MONROE COUNTY SURVEYOR • Trohn Enright-Randolph**

119 W 7th Street, Bloomington, IN 47404 • 812-349-2570 • [surveyorsoffice@co.monroe.in.us](mailto:surveyorsoffice@co.monroe.in.us)

Page 2 of 3



# MONUMENT RECORD

Corner ID: **VanBu\_U23**

## Quarter Corner

Sections 35 & 36 - T08N-R02W, 2nd P.M.  
Van Buren Township, Monroe County, Indiana


**OTHER EVIDENCE:** Describe corner location relative to nearby features and how to reach the corner location – note fences, roads, timber cutting lines, mow lines, clearings, plantings, streams, topo changes, etc.

Stone is located within the fence that surrounds the South Union Church Cemetery +/- 95' west of the church and +/- 225' west of Rockport Rd in a shady area. It can be seen from Duvall Rd but must be accessed from the parking lot south of the cemetery.

**MONUMENT PRESERVATION:** Describe work done to preserve existing monument.

Geodetic controls were captured for the monument. Acidity of stone was tested. "Protect Nearby Survey Markers" sign was set respectably on the north side of the fence facing north. Witnesses were established.

**THEORY OF LOCATION:** Describe the theory of location for acceptance of this monument. Include monument origin and associated uncertainty.

It is believed the stone originates from a survey performed by James H. Spencer performed February 13<sup>th</sup> and 14<sup>th</sup>, 1865 and archived in Land Survey Book 2, Page 118 on file at the Surveyor's Office as RSID004922. A magnetic signal was found on the south side of Ballard Rd. 12.18' north of the monument, which could be the road nail identified as a witness in a survey by Dustin K. Ballard, I-69 Section 4, Segment 8 East Zone Location Control Route Survey (2011), on file at the Recorder's Office as 2011008296.IN. Another Reference on File: Survey by Eric L. Deckard, Alex Deckard Type "E" Administrative Subdivision Final Plat (2021), on file at the Recorder's Office as 2021009651.IN. MCSO used the distances and bearings between VanBu\_U25 and VanBu\_U23, provided in Mr. Deckard's survey, to verify the stone certified here was the same one being held on the Alex Deckard Plat. Historic research has not yet been performed to prove the validity of this monument.

### CERTIFICATION:



Date: 2/21/2023  
Trohn Enright-Randolph  
Monroe County Surveyor



Date: 2/21/2023  
Accepted by the Monroe County  
Surveyor Review Board

